



TIP	300	400	450	510	600	700	750	800
D	62	70	70	80	100	115	115	120
d	30	40	45	50	60	70	75	80
L	45	60	60	60	70	70	70	70
L1	25	30	30	30	30	30	30	30
X	8	10	10	10	10	12	12	12
X1	16	20	20	30	30	35	35	35
n*	3	3	3	3	6	6	6	6

*število izvrtin!